The Commonwealth of Massachusetts

DEPARTMENT OF ENVIRONMENTAL QUALITY ENGINEERING
Division of Solid and Hazardous Waste

MEMORANDUM

JUL 27 1987

TO: Gary Gosbee

DATE: July 20, 1987

FROM: Anne Crawley

SUBJECT: Status Changes for TSDs

The following TSD Status changes have been approved by this Department and confirmed by inspection. All required documentation is attached.

REGION 2	FROM	TO
ATF Davidson MAD046128559	TSD, LQG	Inactive Code: 1
Johnson Steel & Wire MAD094276714	TSD, LQG	Inactive Code: 3
Tessier Machine Co.* MAD067764746	TSD	SQG
Wright G.F. MAD001128719	TSD	SQG
REGION 3		
Matheson Gas MADC66610585	TSD	LQG
REGION 4		
Franklin Pumping Service * MAD084814136	TSD,LQG	SQG Transporter

The following companies have notified as state regulated TSDS in that they store pcb waste for over 90 days. Although this activity is under TOSCA, they are required to notify per 310 CMR 30.370.
ERT MAD054450235
MASS Electric Company MAD980731616

*Notification Error

MEMORANDUM – CHANGE OF STATUS REQUEST

TO: Anne Crawley
      DEQE – DHW
      1 Winter Street
      Boston 02108

FROM: *John F. Kronopolus*

REGION: *Central - Worcester*

DATE: *6/11/87*

DIVISION OF HAZARDOUS WASTE JUL 1 3 '87

NAME OF CO.: *ATF Davidson Co. Inc*
                                Northbridge

MAD# *0 46 128559*

CURRENT STATUS *Generator, TSD*

CHANGE REQUESTED *Out of System*

PROCESS CODES, if TSDF *501, 502, 701*

DATE OF INSPECTION *6/10/87*

FURTHER ACTION NEEDED *No*

CHANGE APPROVED *Yes*

Description of Current Status, changes in processes, listing each code:

This company has left this location (Oct. 1985). It no longer stores hazardous waste in drums or tanks. And no longer treats in tanks. The 6/10/87 inspection revealed <u>No</u> ATF Davidson waste remained on site. This region approves the change to inactive status.

cc: Community official _____